

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
11/16/18 @ 12:00 pm. 65 degrees, hazy skies.
2. REAS Application Date, how many years since REAS application
8/15/17. (1) Year, (3) Months since application. Type III
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
90%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.

Looks good. Very minimal surface cracking. No significant wear even at end done by hand work.
8. Yes No

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Note general or specific problems (include photo name or number and specific location)
None to report.
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s) - NO
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO

Evaluated by [REDACTED]
November 16, 2018