

LIFE CYCLE TRACKING PROGRAM
2nd ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
10/15/19 @ 11:00 am. 70 degrees, hazy skies.
2. REAS Application Date, how many years since REAS application
8/15/17. 2 Years+ since application. Type III

3. Customer and Project Title

[REDACTED]

4. Name of street being tracked (include cross street limits)

[REDACTED]

5. Rate Color from 0-100 in increments of 10 (100-blackest)

80

6. REAS Material Remaining in terms of % (0-100% in increments of 10%)

80-90%

7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.

Micro-cracking throughout, especially in first 20 feet from [REDACTED] and right hand side shoulder entering ramp. No large cracks forming yet.

8. Yes No

- | | | |
|---|---|------------------------|
| | X | Color Inconsistent |
| | X | Unevenness in material |
| X | | Cracks |
| | X | Potholes |
| | X | Raveling |

9. Any utility or other street cuts, other damage (note specific location(s))

NO

10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.

NO

11. Other Comments

None

Evaluated by [REDACTED]
October 15, 2019