

LIFE CYCLE TRACKING PROGRAM
3rd ANNUAL EVALUATION – REPORT AND PHOTOS

1. Date and Time of assessment; temperature and sky conditions
9/01/20 @ 11:15 am, 86 degrees with clear and sunny skies.
2. REAS Application Date, How many years since REAS application
[REDACTED]
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color: 50-100 or "Below 50" in increments of 10 (100 blackest) - Use "Color Rating Guide"
70
6. Cracks: Rate from 0-100: 100-best condition - Use "Percent REAS Remaining Rating Guide"
70
7. Potholes: Rate from 0-100: 100-best condition - Use "Percent REAS Remaining Rating Guide"
100
8. Raveling: Rate from 0-100: 100-best condition - Use "Percent REAS Remaining Rating Guide"
90
9. Rate Percent REAS Remaining (0-100% in increments of 10%)- Use "Percent REAS Remaining Rating Guide"
80% (about 10% surface wear)
10. Any utility or other street cuts, other damage (note specific locations)
NO
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file
NO
12. Other Comments
More surface wear at entrance. A little darker on E/s, a bit inconsistent color. Alligator cracking starting to open up at entrance.

Evaluated by [REDACTED]
September 1, 2020