

LIFE CYCLE TRACKING PROGRAM
2nd ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report; Sky conditions
8/12/19 @ 11:15 am; 75 degrees, sunny and clear
2. REAS Application Date, how many years since REAS application
8/24/17, (2) Years since application. Type I
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
90%
7. Note surface defects such as raveling, spalling, severe cracking and reference specific locations.
8. Yes No

X	Color Inconsistent – last year noted dark longitudinal streaks at spreader box overlaps. Now color has blended well but seams still visible.
X	Unevenness in material
X	Cracks – few transverse and longitudinal, also utility cuts. Look to mostly or all to be pre-existing cracks now reflecting through.
X	Potholes
X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file
NO
11. Other Comments
Some material starting to wear off near intersection (hand work area)

Evaluated by [REDACTED]
August 12, 2019