

LIFE CYCLE TRACKING PROGRAM
3rd ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report; Sky conditions
6/30/20 @ 9:15 am; 65 degrees and cloudy
2. REAS Application Date, how many years since REAS application
8/24/17, almost (3) Years since application. Type I
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**
90
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**
85%
7. **Note surface defects such as raveling, spalling, severe cracking and reference specific locations.**
 - As noted last year, some material starting to wear off near intersection (hand work area), east 1/3 of street for 20 feet long.
 - CDS end holding up well, just a few small areas of wear.
 - Some fines exposed on surface but no raveling.
8. **Yes No**

X	Color Inconsistent.
X	Unevenness in material
X	Cracks – Longitudinal crack along center of and almost entire length of street. Few transverse cracks. All appear to be due to pavement weakness rather than REAS failure.
X	Potholes
X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file
NO
11. Other Comments
Tuesday Is trash pick up day.

Evaluated by [REDACTED]
June 30, 2020