

**LIFE CYCLE TRACKING PROGRAM**  
**10th ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report  
7/02/20, 2:30 pm. 81 degrees and sunny.
2. REAS Application Date, how many years since REAS application  
Estimated 2010; approximately 10 years since application.
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]  
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**  
50
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**  
70%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**  
Both streets still being held together but ride getting a little rough from cracking. Few small pop-outs, potholes previously observed on [REDACTED] have been filled. Surface wearing off.
8. **Yes No**

X	Color Inconsistent
X	Unevenness in material
X	Cracks – many opened, getting wider.
X	Potholes – Most filled. Few pop-outs, some small alligatored areas on [REDACTED] St starting to sink.
X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))  
Utility trench across fill width of [REDACTED], just E/of [REDACTED]
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
NO
11. Other Comments  
**10 Years – CLOSE FILE!**

Evaluated by [REDACTED]  
July 2, 2020