

LIFE CYCLE TRACKING PROGRAM
6TH ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
May 11, 2018 @ 1:30 pm. 63 degrees and cloudy.
2. REAS Application Date, how many years since REAS application
2012 (estimated). 6 Years since REAS Application (believed to be Type II).
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
70
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
80%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
Nothing significant
8. **Yes** **No**

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Note general or specific problems (include photo name or number and specific location)
REAS holding up well after 6 years with good color retention. No evidence of raveling. Some cracking reflecting through but expected.
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s)
No
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
No

Evaluated by [REDACTED]
May 11, 2018