

**LIFE CYCLE TRACKING PROGRAM**  
**8<sup>TH</sup> ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report  
June 10, 2020 @ 11:30 am. 93 degrees, sunny and clear.
2. REAS Application Date, how many years since REAS application  
2012 (estimated). 8 Years since REAS Application (believed to be Type II).
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**  
60
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**  
60-70%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**
8. **Yes No**

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks – moderate cracking throughout.
<input checked="" type="checkbox"/>	Potholes – few potholes at [REDACTED] end, some alligator cracking.
<input checked="" type="checkbox"/>	Raveling
9. Any utility or other street cuts, other damage (note specific location)  
Nothing significant, more than what would be expected after 8 years on an arterial street.
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s))  
NO
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
YES partially. Recently resurfaced from [REDACTED] (see picture #3).

Evaluated by [REDACTED]  
June 10, 2020