

LIFE CYCLE TRACKING PROGRAM
6th ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report; Sky conditions
12/04/18 @ 10:15 am, 52 degrees and mostly sunny skies.
2. REAS Application Date, how many years since REAS application
2012 (estimated), approximately 6-1/2 years since application.
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
60+
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
80%+
7. Note surface defects such as raveling, spalling, severe cracking and reference specific locations
Nothing significant
8. Yes No

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks – moderate reflective cracks, does not appear to be material failure.
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
No
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
No
11. Other comments
REAS material holding up well for 6-1/2 years since application.

Evaluated by [REDACTED]
December 4, 2018