

LIFE CYCLE TRACKING PROGRAM
7th ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report; Sky conditions
10/30/19 @ 5:00 pm, 53 degrees and clear skies.
2. REAS Application Date, how many years since REAS application
2012 (estimated), approximately 7-1/2 years since application.
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**
70
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**
70%
7. **Note surface defects such as raveling, spalling, severe cracking and reference specific locations**
Nothing significant.
8. **Yes No**

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input type="checkbox"/>	Cracks – Some reflective cracking but material seems to be doing well.
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO
11. Other comments
Material doing very well for 7 + years. This off-ramp gets more traffic because of [REDACTED] but seems to be doing well.

Evaluated by [REDACTED]
October 30, 2019