

**LIFE CYCLE TRACKING PROGRAM**  
**6th ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report  
6/01/19, 10:45 am. 78 degrees, clear and sunny.
2. REAS Application Date, how many years since REAS application  
June/July 2013; almost 5 years since application
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**  
60+
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**  
80+
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**  
Heavy cracking and substantial raveling continues
8. **Yes No**

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks – 1-inch wide transverse cracks (pre-existing); some alligator cracking starting to open.
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))  
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
NO
11. Other Comments  
Heavy wear at [REDACTED] end, especially on the north side of the street where cars onto [REDACTED] without stopping.

Evaluated by [REDACTED]  
June 1, 2019