

LIFE CYCLE TRACKING PROGRAM
7th ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
7/02/20, 12:00 pm. 86 degrees and sunny.
2. REAS Application Date, how many years since REAS application
June/July 2013; 7 years since application
3. Customer and Project Title
[REDACTED].
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**
60
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**
70%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**
 - A lot of wear near [REDACTED], heavy wear at [REDACTED] intersection and 100 feet in.
 - Significant wear on edges now.
 - Fines now getting exposed.
8. **Yes No**

X	Color Inconsistent
X	Unevenness in material
X	Cracks – many 1-inch and 2-inch+ wide transverse cracks, some alligator cracking and spider cracking starting to open.
X	Potholes
X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO
11. Other Comments
None

Evaluated by [REDACTED]
July 2, 2020