

LIFE CYCLE TRACKING PROGRAM
6th ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
6/30/20, 12:45 pm. 74 degrees, mostly sunny
2. REAS Application Date, how many years since REAS application
9/2014. Almost 6 years since application.
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**
60 REAS vs 20 conventional
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**
70% REAS vs 30% conventional
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**
8. **Yes No**

| | |
|---|------------------------|
| X | Color Inconsistent |
| X | Unevenness in material |
| X | Cracks |
| X | Potholes |
| X | Raveling |
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO
11. Other Comments
REAS side starting to crack, some wear off at car dealership driveway. REAS still effective, stark contrast vs. poor condition conventional slurry seal.

Evaluated by [REDACTED]
June 30, 2020