

**LIFE CYCLE TRACKING PROGRAM**  
**6<sup>th</sup> ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report  
6/30/20. 10:45 am. 71 degrees, mostly cloudy
2. REAS Application Date, how many years since REAS application  
Estimated October 2014, believed to be double application – Type II over Type II  
PMI Applied 5-1/2 years ago
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**  
60
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**  
70%
7. **Note surface defects such as raveling, spalling, severe cracking and reference specific locations.**
  - 15'x 30' skin patch at 302.
  - Heavy alligating most of street width from 100 feet N/of [REDACTED] to [REDACTED]  
[REDACTED]
8. **Yes No**

X	Color Inconsistent
X	Unevenness in material
X	Cracks – Heavy alligating.
X	Potholes – at [REDACTED] and at 283, few other small pop outs.
X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))  
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
NO
11. Other Comments  
Still holding together well despite heavy alligating throughout.

Evaluated by [REDACTED]  
6/30/20