

**LIFE CYCLE TRACKING PROGRAM**  
**3rd ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report  
5/17/18 @ 3:00 pm, 73 degrees and partly cloudy.
2. REAS Application Date, how many years since REAS application  
August 2015; almost 3 years since application.
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)  
60-70
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)  
80%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.  
Alligator cracking at various locations. Cracking – throughout but nothing large or failing. Color a little light after only 3 years.
8. **Yes No**

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Note general or specific problems (include photo name or number and specific location) None
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s) No
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
No

Evaluated by [REDACTED]  
May 17, 2018