

LIFE CYCLE TRACKING PROGRAM
4th ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
6/01/19, 12:15 pm. 64 degrees, cloudy.
2. REAS Application Date, how many years since REAS application
August 2015; almost 4 years since application.
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**
60 - 70
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**
70-80%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**
Light to moderate cracking throughout but none seen large or failing. Some wider transverse cracks and wider cracks at gutter line with weeds. It doesn't look like crack fill preparations was done. Intersections look good, moderate wear at driveways and short lengths in parking lanes.
8. **Yes No**

X	Color Inconsistent
X	Unevenness in material
X	Cracks – light to moderate throughout, some alligatored locations starting to open up.
X	Potholes
X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO
11. Other Comments
Holding up fairly well.

Evaluated by [REDACTED]
June 1, 2019