

LIFE CYCLE TRACKING PROGRAM
5th ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
7/02/20, 11:45 am. 86 degrees and sunny.
2. REAS Application Date, how many years since REAS application
August 2015; almost 5 years since application
3. Customer and Project Title
██
4. Name of street being tracked (include cross street limits)
██ Double Application: Type II over Type II.
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**
60
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**
70%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**
8. **Yes No**

X	Color Inconsistent
X	Unevenness in material
X	Cracks – Cracks opening wider but no material appears to be popping out or coming off.
X	Potholes
X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO
11. Other Comments
No pop-outs or failures. Ride quality starting to get a bit rough.

Evaluated by ██████████
July 2, 2020