

**LIFE CYCLE TRACKING PROGRAM**  
**2nd ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report; Sky conditions  
12/04/18 @ 12:45 pm, 57 degrees and mostly sunny skies.
2. REAS Application Date, how many years since REAS application  
June 2016, 2-1/2 years since application.
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)  
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)  
90%
7. Note surface defects such as raveling, spalling, severe cracking and reference specific locations  
  
None
8. Yes No

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Only minor reflective cracking.
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))  
No
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
No
11. Other comments  
All looks good, no unusual wear or issues.

Evaluated by [REDACTED]  
December 4, 2018