

# LIFE CYCLE TRACKING PROGRAM

## 2<sup>ND</sup> ANNUAL PHOTOS AND EVALUATION

1. **Date and Time of Report; Note Sky Conditions**  
02/18/2019 – 10:00 AM - Sunny
2. **REAS Application Date, how many years since REAS application**  
November 2016 – 27 months (2.25 Yrs)
3. **Customer and Project Title**  
[REDACTED]
4. **Name of street being tracked (include cross street limits)**  
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100 – blackest)**  
75
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**  
80%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures if applicable**  
Typical transverse and longitudinal reflective cracking.
8. 

<b><u>Yes</u></b>	<b><u>No</u></b>	
	X	Color Inconsistent
	X	Unevenness in Material
X		Cracks
	X	Potholes
	X	Raveling
9. **Any utility or other street cuts, other damage (note specific location(s) and include photo(s))**  
None observed.
10. **Has street been re-slurry sealed or resurfaced? If so, include photos and close out file**  
No.
11. **Other Comments**  
None.

Evaluated by [REDACTED]  
February 18, 2019