

**LIFE CYCLE TRACKING PROGRAM**  
**3rd ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report  
2/21/20, 12:00 pm. 79 degrees, patchy cloudy.
2. REAS Application Date, how many years since REAS application  
November 2016 – 3.25 years since application.
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**  
75
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**  
80%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**
  - Straight aways - good condition.
  - Moderate to heavy wear on edges of intersections with gated communities. Some random wear throughout these intersections.
  - Heavy wear throughout major intersections – with [REDACTED]
8. **Yes No**

X	Color Inconsistent
X	Unevenness in material
X	Cracks – Transverse and Longitudinal cracks, especially in intersections.
X	Potholes
X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))  
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
NO
11. Other Comments  
None

Evaluated by [REDACTED]  
February 21, 2020