

LIFE CYCLE TRACKING PROGRAM
1ST ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
May 11, 2018 @ 12:00 pm. 61 degrees and cloudy.
2. REAS Application Date, how many years since REAS application
5/19/17. One year since application.
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
90+ %
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
Nothing significant
8. Yes No

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Note general or specific problems (include photo name or number and specific location)
Very few cracks, one longitudinal centerline crack between [REDACTED] of note. No shedding, very few small spalls.
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s)
None noted
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
No

Evaluated by [REDACTED]
May 11, 2018