

LIFE CYCLE TRACKING PROGRAM
2nd ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report; Sky conditions
5/31/19 @ 12:45 pm; 63 degrees and cloudy
2. REAS Application Date, how many years since REAS application
5/19/17, 2 years since application of Type I REAS
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
90%
7. Note surface defects such as raveling, spalling, severe cracking and reference specific locations.
8. **Yes** **No**
 - Color Inconsistent
 - Unevenness in material
 - Cracks – Few opened up but no cracking sealing done
 - Potholes
 - Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file
NO
11. Other Comments
Moderate wear off at [REDACTED] end especially E/B parking lane and at [REDACTED] intersection

Evaluated by [REDACTED]
May 31, 2019