

LIFE CYCLE TRACKING PROGRAM
3rd ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report; Sky conditions
7/3/20 @ 11:00 am; 71 degrees and sunny
2. REAS Application Date, how many years since REAS application
5/19/17, 3 years since application of Type I REAS
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
[REDACTED]
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**
80
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**
70%
7. **Note surface defects such as raveling, spalling, severe cracking and reference specific locations.**
 - Worst wear [REDACTED] – both sides.
 - Significant wear at [REDACTED] intersection.
 - Some wear on N/S from [REDACTED] to 746 (wheel track) and across the street at diagonal parking.
8. **Yes No**

X	Color Inconsistent
X	Unevenness in material
X	Cracks – Few opened up but no cracking sealing done
X	Potholes
X	Raveling – some raveling at wear locations.
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file
NO
11. Other Comments
None

Evaluated by [REDACTED]
July 3, 2020