

**LIFE CYCLE TRACKING PROGRAM**  
**3rd ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report  
7/09/20 @ 2:30 pm. 85 degrees, clear and sunny
2. REAS Application Date, how many years since REAS application  
6/16/17, 3 years since application
3. Customer and Project Title  
██
4. Name of street being tracked (include cross street limits)  
██
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**  
80
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**  
90%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.** See below
8. **Yes No**

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks – few ¼ inch cracks, with larger cracks approaching ██████████ - longitudinal and lateral. Lighter cracking throughout. No crack fill prep done.
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))  
No new work noted.
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
NO
11. Other Comments  
- Some wear at ██████████, some driveways both sides, W/S parking lane for 100 feet near ██████████

Evaluated by ██████████  
July 9, 2020