

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
7/23/18 @ 11:30 am. 89 degrees, sunny and clear
2. REAS Application Date, how many years since REAS application
7/20/17, (1) year since application
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
70-80%. Similar to "Immediately After" condition when street was opened too early and a substantial amount of material was picked up in many areas over entire block
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
Many missing patches of material throughout block; no repairs ever made
8. Yes No

X	Color Inconsistent
X	Unevenness in material
X	Cracks
X	Potholes
X	Raveling
9. Note general or specific problems (include photo name or number and specific location)
See #7
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s))
No
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
No

Evaluated by [REDACTED]
July 23, 2018