

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
8/13/18 @ 10:30 am. 80 degrees, sunny with clear skies.
2. REAS Application Date, how many years since REAS application
8/10/17. (1) Year since application.
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
80
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
90%+
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
8. Yes No

X	Color Inconsistent
X	Unevenness in material
X	Cracks
X	Potholes
X	<u>Raveling</u> – minor. Southern ¼ of street light ravel between 4402-4414.
9. Note general or specific problems (include photo name or number and specific location)
None
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s))
Yes. Large steel plate near end of cul-de-sac (see picture #4)
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
No

Evaluated by [REDACTED]
August 13, 2018