

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
10/17/18, 11:00 am. 78 degrees, sunny with clear skies.
2. REAS Application Date, how many years since REAS application
8/14/17. (1) Year and (2) Months since application. Type II
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
90%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
8.

<u>Yes</u>	<u>No</u>	
	X	Color Inconsistent
	X	Unevenness in Material
X		<u>Cracks</u> – surface cracking throughout
	X	Potholes
	X	Raveling
9. Note general or specific problems (include photo name or number and specific location)
 - Rough longitudinal overlap seam westerly third of street from 51385 to Ave [REDACTED] with material missing in seam in some areas
 - Some material wearing off at [REDACTED] end
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s) - NO
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO

Evaluated by [REDACTED]
October 17, 2018