

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
10/17/18, 12:15 am. 80 degrees, sunny with clear skies.
2. REAS Application Date, how many years since REAS application
10/3 and 10/4, 2017. (1) Year since application. Type II
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
90%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
8.

<u>Yes</u>	<u>No</u>	
X		Color Inconsistent
X		Unevenness in material
X		Cracks
X		Potholes
X		Raveling
9. Note general or specific problems (include photo name or number and specific location)
 - @ [REDACTED] Project limit at mid-intersection where material doing well. Some material coming off at median island nose
 - @ [REDACTED] Material wearing off for 30 feet from intersection, especially west bound (N/S)
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s)) - NO
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO

Evaluated by [REDACTED]
October 17, 2018