

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report; Sky conditions
11/27/18 @ 11:00 am, 74 degrees with hazy sunshine.
2. REAS Application Date, how many years since REAS application
11/29/17, 1 year since application.
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
80-90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
90+%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
8.

| <u>Yes</u> | <u>No</u> | |
|------------|-----------|--|
| | X | Color Inconsistent |
| | X | Unevenness in material |
| X | | Cracks – reflective cracks, not material cracking. No crack seal done. |
| | X | Potholes |
| | X | Raveling |
9. Note general or specific problems (include specific locations)
Material is performing well despite minimal prep work, including no crack fill.
10. Any utility or other street cuts, other damage (note specific location(s))
No
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
No

Evaluated by [REDACTED]
November 27, 2018