

LIFE CYCLE TRACKING PROGRAM
2nd ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report; Sky conditions
11/19/19 @ 12:15 pm, 80 degrees and partly cloudy.
2. REAS Application Date, how many years since REAS application
11/29/17, 2 years since application.
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
80-90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
80%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
 - Significant wear since last year. Long patterns at seams where box chatter showing (3 seams). Wear especially prevalent from Bianca.
 - Cracking opening more throughout, many ½ inch to 1 inch wide and more. Very wide cracks at south side intersection with [REDACTED] where digout repair work should have been done.
8.

<u>Yes</u>	<u>No</u>	
X		Color Inconsistent
X		Unevenness in material
X		Cracks – See comments under #7 above.
X		Potholes
X		Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO
11. Other Comments
One picture angle added – looking east from W/S crosswalk at [REDACTED] (#2 – see Revised Map).

Evaluated by [REDACTED]
November 19, 2019