

**LIFE CYCLE TRACKING PROGRAM**  
**1<sup>st</sup> ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report; Sky conditions  
4/22/19 @ 11:15 am; 64 degrees and sunny skies
2. REAS Application Date, how many years since REAS application  
4/25/18, 1 year since application of Type II REAS
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]  
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)  
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)  
90%
7. Note surface defects such as raveling, spalling, severe cracking and reference specific locations.
8. 

<u>Yes</u>	<u>No</u>	
X		Color Inconsistent
X		Unevenness in material
X		Cracks
X		Potholes – (1) small pothole at 7823
X		Raveling – some raveling on E/S gutter lane near [REDACTED]
9. Any utility or other street cuts, other damage (note specific location(s))  
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file  
NO
11. Other Comments  
Street surface a little "chatterly" (rough) throughout

Evaluated by [REDACTED]  
April 22, 2019