

LIFE CYCLE TRACKING PROGRAM
2nd ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
7/06/20 @ 11:00 am. 84 degrees and sunny
2. REAS Application Date, how many years since REAS application
6/27/18, 2 years since application
3. Customer and Project Title
████████████████████████████████████████
4. Name of street being tracked (include cross street limits)
████████████████████████████████████████████████████████████████████████████████
████████
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**
90
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**
90%
7. **Note surface defects such as raveling, spalling, severe cracking and reference with pictures.**
 - Just a little wear starting at ██████ end (handwork).
 - Material at few areas in parking lanes starting to wear off.
 - Fine cracking just starting to appear.
8. **Yes No**

X	Color Inconsistent
X	Unevenness in material
X	Cracks
X	Potholes
X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
None
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
No
11. Other Comments
Pictures # 2 and #3 near 3057 driveway.

Evaluated by ██████████
July 6, 2020