

**LIFE CYCLE TRACKING PROGRAM**  
**1st ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report; Sky conditions  
8/12/19 @ 1:00 pm; 79 degrees, sunny and clear
2. REAS Application Date, how many years since REAS application  
8/13/18, (1) Year since application.
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)  
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)  
90%
7. Note surface defects such as raveling, spalling, severe cracking and reference specific locations.
8. Yes No

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))  
NO but several USA markings about ¾ point down from [REDACTED]
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file  
NO
11. Other Comments  
Looks good!

Evaluated by [REDACTED]  
August 12, 2019