

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
8/21/19 @ 11:00 am. 81 degrees, sunny and clear.
2. REAS Application Date, how many years since REAS application
8/29/18, 1 year since application
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
90+
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
95%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
Nothing significant.
8. Yes No

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
 - No, but USA markings between the west and east [REDACTED] intersections.
 - Temporary 2' x 3' AC patch on the north end of this same block.
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
No
11. Other Comments
Looks good.

Evaluated by [REDACTED]
August 21, 2019