

**LIFE CYCLE TRACKING PROGRAM**  
**1st ANNUAL - PHOTOS AND EVALUATION**

1. Date and Time of report  
10/16/19 @ 12:30 pm. 89 degrees, hazy skies.
2. REAS Application Date, how many years since REAS application  
10/22/18. 1 Year since application.
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)  
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)  
90+%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
  - A little bit of hand work coming off at [REDACTED] end.
  - A few micro cracks starting to reflect through.
  - A little raveling at [REDACTED] and [REDACTED] N/S intersections, needs sweeping.
8. Yes No

X	Color Inconsistent
X	Unevenness in material
X	Cracks – a bit of micro-cracking
X	Potholes
X	Raveling – some at [REDACTED] intersections
9. Any utility or other street cuts, other damage (note specific location(s))  
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.  
NO
11. Other Comments  
Mid-block pictures at center of [REDACTED] intersection.

Evaluated by [REDACTED]  
October 16, 2019