

## **LIFE CYCLE TRACKING PROGRAM**

### **2nd ANNUAL EVALUATION – REPORT AND PHOTOS**

1. Date and Time of assessment; temperature and sky conditions  
9/15/20 @ 1:30 pm, 83 degrees with hazy sun.
2. REAS Application Date, How many years since REAS application  
10/22/18, 2 Years since application. Type II REAS.
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. **Rate Color:** 50-100 or "Below 50" in increments of 10 (100 blackest) -  
Use "Color Rating Guide"  
90
6. **Cracks: Rate from 0-100:** 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
90. Some fine cracks opening (light to moderate amount, mostly less than ¼-inch).
7. **Potholes: Rate from 0-100:** 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
100 – none.
8. **Raveling: Rate from 0-100:** 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
90. Some raveling on S/S parking lane approaching [REDACTED]
9. **Rate Percent REAS Remaining** (0-100% in increments of 10%)-  
Use "Percent REAS Remaining Rating Guide"  
85%
10. Any utility or other street cuts, other damage (note specific locations)  
NO
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file  
NO
12. Other Comments  
Some hand worked ends starting to noticeably wear, heaviest at [REDACTED] (-5%).

Evaluated by [REDACTED]  
September 15, 2020