

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
1/29/20 @ 11:00 am. 66 degrees, sunny and clear with moderate winds.
2. REAS Application Date, how many years since REAS application
1/10/19, 1 year since application
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
90
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
90%+
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
8.

<u>Yes</u>	<u>No</u>	
	X	Color Inconsistent
	X	Unevenness in material
X		Cracks – Many pre-existing cracks reflecting through and opened up. Alligatored areas opened up.
	X	Potholes
	X	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
NO
11. Other Comments
 - Premature wear of 2 tire tracks, center of street. Gutter lanes look discolored but maybe only dirt.
 - Speed humps not slurried.

Evaluated by [REDACTED]
January 29, 2020