

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report; Sky conditions
7/08/20 @ 10:30 am; 95 degrees and sunny.
2. REAS Application Date, how many years since REAS application
5/07/19, 1 year since application of Type II REAS
3. Customer and Project Title
██
4. Name of street being tracked (include cross street limits)
██
5. **Rate Color from 0-100 in increments of 10 (100-blackest)**
90
6. **REAS Material Remaining in terms of % (0-100% in increments of 10%)**
95%
7. **Note surface defects such as raveling, spalling, severe cracking and reference specific locations.**
8. **Yes No**

<input checked="" type="checkbox"/>	Color Inconsistent
<input checked="" type="checkbox"/>	Unevenness in material
<input checked="" type="checkbox"/>	Cracks – Very fine cracks starting to appear.
<input checked="" type="checkbox"/>	Potholes
<input checked="" type="checkbox"/>	Raveling
9. Any utility or other street cuts, other damage (note specific location(s))
NO
10. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file
NO
11. Other Comments
None, looks pretty good.

Evaluated by ██████████
July 8, 2020