

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL EVALUATION – REPORT AND PHOTOS

1. Date and Time of assessment; temperature and sky conditions
9/01/20 @ 12:15 am, 88 degrees with clear and sunny skies.
2. REAS Application Date, How many years since REAS application
6/20/19, 1 Year since application. Type II
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color: 50-100 or "Below 50" in increments of 10 (100 blackest) -
Use "Color Rating Guide"
90
6. Cracks: Rate from 0-100: 100-best condition -
Use "Percent REAS Remaining Rating Guide"
75. Low to moderate amount of cracking but some opening up to ½ - 1 inch wide.
7. Potholes: Rate from 0-100: 100-best condition -
Use "Percent REAS Remaining Rating Guide"
100
8. Raveling: Rate from 0-100: 100-best condition -
Use "Percent REAS Remaining Rating Guide"
90. Some raveling in both parking lanes, especially south of [REDACTED].
9. Rate Percent REAS Remaining (0-100% in increments of 10%)-
Use "Percent REAS Remaining Rating Guide"
85% (very little surface wear)
10. Any utility or other street cuts, other damage (note specific locations)
NO
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out
file
NO
12. Other Comments
None.

Evaluated by [REDACTED]
September 1, 2020