

**LIFE CYCLE TRACKING PROGRAM**  
**1st ANNUAL EVALUATION – REPORT AND PHOTOS**

1. Date and Time of assessment; temperature and sky conditions  
9/23/20 @ 12:45 pm, 101 degrees with clear and sunny skies.
2. REAS Application Date, How many years since REAS application  
9/13/19, 1 Year since application. Type II
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. Rate Color: 50-100 or "Below 50" in increments of 10 (100 blackest) -  
Use "Color Rating Guide"  
90+
6. Cracks: Rate from 0-100: 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
95. Few fine cracks, mostly near edges.
7. Potholes: Rate from 0-100: 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
95 – few large pick-ups at [REDACTED] driveway (behind picture #3)
8. Raveling: Rate from 0-100: 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
95. Some raveling in between median islands (end of left turn pocket lanes).
9. Rate Percent REAS Remaining (0-100% in increments of 10%)-  
Use "Percent REAS Remaining Rating Guide"  
90% (very little to no surface wear)
10. Any utility or other street cuts, other damage (note specific locations)  
NO
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out  
file  
NO
12. Other Comments  
Looks good!

Evaluated by [REDACTED]  
September 23, 2020