

# LIFE CYCLE TRACKING PROGRAM

## 1st ANNUAL EVALUATION – REPORT AND PHOTOS

1. Date and Time of assessment; temperature and sky conditions  
9/23/20 @ 12:15 pm, 100 degrees with clear and sunny skies.
2. REAS Application Date, How many years since REAS application  
9/13/19, 1 Year since application. Type I
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. Rate Color: 50-100 or "Below 50" in increments of 10 (100 blackest) -  
Use "Color Rating Guide"  
90
6. Cracks: Rate from 0-100: 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
90. Few fine cracks opening, mostly towards [REDACTED] Some wider cracks that were crack filled starting to open just a bit.
7. Potholes: Rate from 0-100: 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
100 – None.
8. Raveling: Rate from 0-100: 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
100 – None.
9. Rate Percent REAS Remaining (0-100% in increments of 10%)-  
Use "Percent REAS Remaining Rating Guide"  
95% (very little to no surface wear)
10. Any utility or other street cuts, other damage (note specific locations)  
NO
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file  
NO
12. Other Comments
  - Surface a bit chattery in places, Ride a bit rough in places, not slurry related.
  - Handworked areas and driveways not wearing off.

Evaluated by [REDACTED]  
September 23, 2020