

LIFE CYCLE TRACKING PROGRAM
7th ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
5/24/18 @ 2:00 pm. 66 degrees, overcast
2. REAS Application Date, how many years since REAS application
REAS applied approximately 2011. Approximately 7 years since application
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
60
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
60 – 70%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
8.

<u>Yes</u>	<u>No</u>	
	X	Color Inconsistent
	X	Unevenness in material
X		Cracks (Moderate)
	X	Potholes
	X	Raveling
9. Note general or specific problems (include photo name or number and specific location)
NA
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s)
NA
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
No

Evaluated by [REDACTED]
May 24, 2018