

LIFE CYCLE TRACKING PROGRAM
1st ANNUAL - PHOTOS AND EVALUATION

1. Date and Time of report
4/20/18, 1:00 pm. 77 degrees, clear and sunny.
2. REAS Application Date, how many years since REAS application
4/18 and 4/19, 2017. 1 year since application
3. Customer and Project Title
[REDACTED]
4. Name of street being tracked (include cross street limits)
[REDACTED]
5. Rate Color from 0-100 in increments of 10 (100-blackest)
80
6. REAS Material Remaining in terms of % (0-100% in increments of 10%)
80%
7. Note surface defects such as raveling, spalling, severe cracking and reference with pictures.
8.

<u>Yes</u>	<u>No</u>	
	X	Color Inconsistent
	X	Unevenness in material
X		Cracks
	X	Potholes
X		Raveling
9. Note general or specific problems (include photo name or number and specific location)
Heavy cracking and substantial raveling over length of street, not just cul-de-sac.
10. Any utility or other street cuts, other damage (note specific location(s) and include photo(s) No
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file.
No

Evaluated by [REDACTED]
April 20, 2018