

**LIFE CYCLE TRACKING PROGRAM**  
**3rd ANNUAL EVALUATION – REPORT AND PHOTOS**

1. Date and Time of assessment; temperature and sky conditions  
8/25/20 @ 11:15 am, 80 degrees with clear and sunny skies.
2. REAS Application Date, How many years since REAS application  
7/20/17, (3) years since Type I application.
3. Customer and Project Title  
[REDACTED]
4. Name of street being tracked (include cross street limits)  
[REDACTED]
5. Rate Color: 50-100 or "Below 50" in increments of 10 (100 blackest) -  
Use "Color Rating Guide"  
70
6. Cracks: Rate from 0-100: 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
65 – 3 different alligatored areas near [REDACTED] end (W/S driveway, E/S driveway, center of street (sunken)). Light cracking opening throughout but not significant.
7. Potholes: Rate from 0-100: 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
90 - Starting at alligatored areas.
8. Raveling: Rate from 0-100: 100-best condition -  
Use "Percent REAS Remaining Rating Guide"  
100
9. Rate Percent REAS Remaining (0-100% in increments of 10%)-  
Use "Percent REAS Remaining Rating Guide"  
60% - multiple pickups when street was opened too early, moderate to heavy wear at both ends and at multiple driveways, alley entrances.
10. Any utility or other street cuts, other damage (note specific locations)  
NO
11. Has street been re-slurry sealed or resurfaced? If so, include photos and close out file  
NO
12. Other Comments  
None

Evaluated by [REDACTED]  
August 25, 2020